

### Front Bumper

|   |   |   |                       |                     |          |     |    |
|---|---|---|-----------------------|---------------------|----------|-----|----|
| 1 | E | 6 | Cover,Front Bumper    | 62022JA040          | \$320.87 | 2.0 | SM |
| 2 | L | 6 | 13 Cover,Front Bumper | Refinish            |          | 3.7 | RF |
|   |   |   |                       | 2.6 Surface         |          |     |    |
|   |   |   |                       | 0.6 Two-stage setup |          |     |    |
|   |   |   |                       | 0.5 Two-stage       |          |     |    |

### Front End Panel And Lamps

|   |    |    |                          |                |  |     |    |
|---|----|----|--------------------------|----------------|--|-----|----|
| 3 | RI | 41 | Headlamp Assy,Halogen LT | R & I Assembly |  | 0.2 | SM |
| 4 | RI | 42 | Headlamp Assy,Halogen RT | R & I Assembly |  | INC | SM |

### Front Body And Windshield

|   |   |     |                 |               |          |     |    |
|---|---|-----|-----------------|---------------|----------|-----|----|
| 5 | E | 104 | Fender,Front RT | 63100ZN55A    | \$276.97 | 1.9 | SM |
| 6 | L | 104 | Fender,Front RT | Refinish      |          | 3.2 | RF |
|   |   |     |                 | 2.2 Surface   |          |     |    |
|   |   |     |                 | 0.5 Edge      |          |     |    |
|   |   |     |                 | 0.5 Two-stage |          |     |    |

### Front Body Interior Sheetmetal

|   |   |     |                          |            |         |     |    |
|---|---|-----|--------------------------|------------|---------|-----|----|
| 7 | E | 108 | 01 Skirt,Inner Fender RT | 63840JA000 | \$72.68 | INC | SM |
|---|---|-----|--------------------------|------------|---------|-----|----|

### Front Suspension

|   |   |     |                    |                  |  |     |    |
|---|---|-----|--------------------|------------------|--|-----|----|
| 8 | N | 970 | Susp Align,4 Wheel | Additional Labor |  | 2.3 | ME |
|---|---|-----|--------------------|------------------|--|-----|----|

### Front Doors

|    |   |     |                         |               |          |     |    |
|----|---|-----|-------------------------|---------------|----------|-----|----|
| 9  | E | 208 | Door Shell,Front RT     | 801009HA0A    | \$626.85 | 5.7 | SM |
| 10 | L | 208 | Door Shell,Front RT     | Refinish      |          | 3.5 | RF |
|    |   |     |                         | 1.9 Surface   |          |     |    |
|    |   |     |                         | 1.0 Edge      |          |     |    |
|    |   |     |                         | 0.6 Two-stage |          |     |    |
| 11 | E | 272 | Mldg,Front Door Belt RT | 80820JA01A    | \$80.17  | INC | SM |

### Rear Doors

|    |   |     |                    |               |  |      |    |
|----|---|-----|--------------------|---------------|--|------|----|
| 12 | I | 288 | Door Shell,Rear RT | Repair        |  | 3.0* | SM |
| 13 | L | 288 | Door Shell,Rear RT | Refinish      |  | 2.0  | RF |
|    |   |     |                    | 1.7 Surface   |  |      |    |
|    |   |     |                    | 0.3 Two-stage |  |      |    |

### Quarter And Rocker Panel

|    |    |     |                              |                |  |      |    |
|----|----|-----|------------------------------|----------------|--|------|----|
| 14 | BR | 261 | 10 Panel,Bodyside Otr Upr RT | Blend Refinish |  | 1.2* | RF |
|    |    |     |                              | 0.2 Two-stage  |  |      |    |
| 15 | BR | 226 | Deflector,Rocker Panel RT    | Blend Refinish |  | 0.7  | RF |
|    |    |     |                              | 0.5 Blend      |  |      |    |
|    |    |     |                              | 0.2 Two-stage  |  |      |    |
| 16 | RI | 226 | Deflector,Rocker Panel RT    | R & I Assembly |  | INC  | SM |
| 17 | I  | 348 | Panel,Quarter RT             | Repair         |  | 8.0* | SM |
| 18 | L  | 348 | Panel,Quarter RT             | Refinish       |  | 2.4  | RF |
|    |    |     |                              | 2.0 Surface    |  |      |    |
|    |    |     |                              | 0.4 Two-stage  |  |      |    |

### Inner Quarter & Panels

|    |   |     |                         |            |         |     |    |
|----|---|-----|-------------------------|------------|---------|-----|----|
| 19 | E | 412 | Shield,Quarter Panel RT | 76748JA000 | \$62.72 | 0.6 | SM |
|----|---|-----|-------------------------|------------|---------|-----|----|

### Rear Bumper

|    |   |     |                       |                  |  |      |    |
|----|---|-----|-----------------------|------------------|--|------|----|
| 20 | N | 566 | Rear Bumper Cover R&I | Additional Labor |  | 1.5  | SM |
| 21 | I | 566 | Cover,Rear Bumper     | Repair           |  | 1.0* | SM |
| 22 | L | 566 | Cover,Rear Bumper     | Refinish         |  | 3.1  | RF |
|    |   |     |                       | 2.6 Surface      |  |      |    |
|    |   |     |                       | 0.5 Two-stage    |  |      |    |

### Rear Body, Lamps And Floor Pan

|                       |    |     |                            |                  |           |      |     |
|-----------------------|----|-----|----------------------------|------------------|-----------|------|-----|
| 23                    | RI | 534 | Taillamp Assembly RT       | R & I Assembly   |           | INC  | SM  |
| <b>Manual Entries</b> |    |     |                            |                  |           |      |     |
| 24                    | EC | M03 | Flex Additive              | Replace Economy  | \$18.00*  |      | RF  |
| 25                    | EC | M04 | Undercoating               | Replace Economy  | \$12.00*  | 0.3* | RF  |
| 26                    | EC | M05 | Rustproofing               | Replace Economy  | \$12.00*  | 0.3* | RF  |
| 27                    | EC | M14 | Corrosion Protection       | Replace Economy  | \$12.00*  | 0.5* | RF  |
| 28                    | L  | M15 | Color Tint                 | Refinish         |           | 0.5* | RF  |
| 29                    | BR | M16 | Color Blend                | Blend Refinish   |           | 1.0* | RF  |
| 30                    | EC | M17 | Cover Car Exterior         | Replace Economy  | \$121.00* | 0.3* | RF  |
| 31                    | N  | M28 | Battery                    | Additional Labor |           | 0.3* | ME* |
| 32                    | N  | M58 | Clean For Delivery         | Additional Labor | \$15.00*  | 0.5* | SM  |
| 33                    | EC | M60 | Hazardous Waste Removal    | Replace Economy  | \$12.00*  | 0.3* | SM  |
| 34                    | L  | M66 | Color Sand And Buff        | Refinish         |           | 2.0* | RF  |
| 35                    | N  | M67 | Reset Electrical Component | Additional Labor |           | 0.5* | ME* |
| 36                    | EC | M70 | Cover Car Interior         | Replace Economy  | \$12.00*  | 0.3* | RF  |
| 37                    | L  |     | MASK FOR PRIME             | Refinish         | \$15.00*  | 0.5* | RF* |
| <b>37 Items</b>       |    |     |                            |                  |           |      |     |

**MC Message**

01 CALL DEALER FOR EXACT PART # / PRICE  
10 INCLUDES AUDATEX TIME TO CLEAR ENTIRE PANEL  
13 INCLUDES 0.6 HOURS FIRST PANEL TWO-STAGE ALLOWANCE

**Estimate Total & Entries**

|                         |          |             |            |
|-------------------------|----------|-------------|------------|
| Gross Parts             |          | \$1,440.26  |            |
| Other Parts             |          | \$229.00    |            |
| Paint Materials         |          | \$765.00    |            |
| Parts & Material Total  |          |             | \$2,434.26 |
| Tax on Parts & Material | @ 7.000% |             | \$170.40   |
| <b>Labor</b>            |          |             |            |
|                         | Rate     | Replace Hrs | Repair Hrs |
| Sheet Metal (SM)        | \$50.00  | 10.7        | 14.0       |
| Mech/Elec (ME)          | \$55.00  |             | 3.1        |
| Frame (FR)              | \$55.00  |             |            |
| Refinish (RF)           | \$50.00  | 25.5        |            |
| Paint Materials         | \$30.00  |             |            |
| Labor Total             |          | 53.3 Hours  |            |
| Tax on Labor            | @ 7.000% |             | \$187.64   |
| Gross Total             |          |             | \$5,472.80 |
| Net Total               |          |             | \$5,472.80 |

Alternate Parts Y/00/00/00/00 CUM 00/00/00/00/00 Zip Code: 07105 Default

Audatex Estimating 7.0.019 ES 07/10/2013 08:17 AM REL 7.0.019 DT 06/01/2013 DB 07/08/2013  
Copyright (C) 2013 Audatex North America, Inc.

3.8 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA.  
ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

# Preliminary Estimate

Job Number:

Vehicle: 2007 NISS ALTIMA 4D SED 4-2.5L-FI

| Line | Oper | Description                      | Part Number | Qty | Extended Price \$ | Labor | Paint |
|------|------|----------------------------------|-------------|-----|-------------------|-------|-------|
| 1    |      | <b>FRONT BUMPER</b>              |             |     |                   |       |       |
| 2    | **   | Repl A/M CAPA Bumper cover       | 62022JA040  | 1   | 168.33            | 1.9   | 2.8   |
| 3    |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 1.1   |
| 4    |      | Repl RT Hole cover w/o fog lamps | 62256JA01A  | 1   | 20.55             | Incl. | 0.0   |
| 5    |      | <b>FRONT LAMPS</b>               |             |     |                   |       |       |
| 6    |      | R&I RT Headlamp assy             |             | 0   | 0.00              | 0.3   | 0.0   |
| 7    |      | Repl Aim headlamps               |             | 1   | 0.00              | 0.5   | 0.0   |
| 8    |      | <b>RADIATOR SUPPORT</b>          |             |     |                   |       |       |
| 9    |      | Repl Lower shield                | 75890JA00E  | 1   | 39.58             | 0.3   | 0.0   |
| 10   |      | Repl Lower shield clip #1        | 0155309241  | 3   | 4.89              | 0.0   | 0.0   |
| 11   |      | Repl Lower shield clip #2        | 0155305323  | 4   | 4.32              | 0.0   | 0.0   |
| 12   |      | <b>FENDER</b>                    |             |     |                   |       |       |
| 13   | *    | Rpr RT Fender                    |             | 0   | 0.00              | 1.5   | 1.8   |
| 14   |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 0.7   |
| 15   |      | Repl RT Stay                     | 63180JA030  | 1   | 17.03             | 0.2   | 0.2   |
| 16   |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 0.1   |
| 17   |      | Repl RT Fender liner             | 63840JA000  | 1   | 72.68             | 0.4   | 0.0   |
| 18   |      | <b>FRONT DOOR</b>                |             |     |                   |       |       |
| 19   | *    | Rpr RT Door shell (HSS)          |             | 0   | 0.00              | 8.0   | 2.2   |
| 20   |      | Overlap Major Adj. Panel         |             | 0   | 0.00              | 0.0   | -0.4  |
| 21   |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 0.4   |
| 22   |      | R&I RT Belt w/strip              |             | 0   | 0.00              | 0.3   | 0.0   |
| 23   | *    | R&I RT Body side mldg            |             | 0   | 0.00              | 0.3   | 0.0   |
| 24   |      | R&I RT R&I mirror                |             | 0   | 0.00              | 0.3   | 0.0   |
| 25   |      | R&I RT Handle, outside black     |             | 0   | 0.00              | 0.4   | 0.0   |
| 26   |      | R&I RT R&I trim panel            |             | 0   | 0.00              | 0.5   | 0.0   |
| 27   |      | <b>REAR DOOR</b>                 |             |     |                   |       |       |
| 28   | *    | Rpr RT Door shell (HSS)          |             | 0   | 0.00              | 1.0   | 2.2   |
| 29   |      | Overlap Major Adj. Panel         |             | 0   | 0.00              | 0.0   | -0.4  |
| 30   |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 0.4   |
| 31   |      | R&I RT Belt w/strip              |             | 0   | 0.00              | 0.3   | 0.0   |
| 32   | *    | R&I RT Body side mldg            |             | 0   | 0.00              | 0.3   | 0.0   |
| 33   |      | R&I RT Handle, outside black     |             | 0   | 0.00              | 0.4   | 0.0   |
| 34   |      | R&I RT R&I trim panel            |             | 0   | 0.00              | 0.4   | 0.0   |
| 35   |      | <b>QUARTER PANEL</b>             |             |     |                   |       |       |
| 36   | *    | Rpr RT Quarter panel             |             | 0   | 0.00              | 4.0   | 2.2   |
| 37   |      | Overlap Major Adj. Panel         |             | 0   | 0.00              | 0.0   | -0.4  |
| 38   |      | Add for Clear Coat               |             | 0   | 0.00              | 0.0   | 0.4   |
| 39   |      | R&I RT Wheelhouse liner          |             | 0   | 0.00              | 0.4   | 0.0   |
| 40   |      | <b>REAR BODY &amp; FLOOR</b>     |             |     |                   |       |       |
| 41   |      | R&I RT Trunk side panel          |             | 0   | 0.00              | 0.3   | 0.0   |
| 42   |      | R&I Rear panel trim              |             | 0   | 0.00              | 0.2   | 0.0   |



# Preliminary Estimate

Job Number:

Vehicle: 2007 NISS ALTIMA 4D SED 4-2.5L-FI

|                  |                    |      |   |            |   |               |             |             |
|------------------|--------------------|------|---|------------|---|---------------|-------------|-------------|
| 43               | <b>REAR LAMPS</b>  |      |   |            |   |               |             |             |
| 44               | **                 | Repl | A/M CAPA RT Combo lamp assy               | 26550ZN50A | 1 | 124.62        | 0.4         | 0.0         |
| 45               | <b>REAR BUMPER</b> |      |   |            |   |               |             |             |
| 46               | *                  | Rpr  | Bumper cover                              |            | 0 | 0.00          | 1.5         | 3.2         |
| 47               |                    |      | Add for Clear Coat                        |            | 0 | 0.00          | 0.0         | 1.3         |
| 48               |                    |      | O/H bumper assy                           |            | 0 | 0.00          | 2.1         | 0.0         |
| 49               |                    | R&I  | RT Mud guard                              |            | 0 | 0.00          | Incl.       | 0.0         |
| 50               | #                  | Rpr  | Color Sand & Buff Panel                   |            | 0 | 0.00          | 0.0         | 1.5         |
| 51               | #                  | Rpr  | Clean & retape mlds                       |            | 0 | 0.00          | 0.5         | 0.0         |
| 52               | #                  | Rpr  | Back Tape Jambs (.3 per jamb)             |            | 0 | 0.00          | 0.3         | 0.0         |
| 53               | #                  | Rpr  | Clean For Delivery                        |            | 0 | 0.00          | 0.5         | 0.0         |
| 54               | #                  | Rpr  | Prep bumper for refinishing (raw plastic) |            | 0 | 0.00          | 0.5         | 0.0         |
| 55               | #                  | Repl | Flex Additive                             |            | 1 | 12.00 T       | 0.0         | 0.0         |
| 56               | #                  | Repl | Apply Corrosion Protection                |            | 1 | 7.00 T        | 0.3         | 0.0         |
| 57               | #                  | Repl | Car Cover                                 |            | 1 | 5.00          | 0.3         | 0.0         |
| 58               | #                  | Subl | E.P.A. Waste Removal Charge               |            | 1 | 5.00          | 0.0         | 0.0         |
| 59               | #                  | Subl | Misc Clips/Fasteners/Rivets               |            | 1 | 21.00         | 0.0         | 0.0         |
| <b>SUBTOTALS</b> |                    |      |   |            |   | <b>502.00</b> | <b>28.6</b> | <b>19.3</b> |

## ESTIMATE TOTALS

| Category           | Basis       |   | Rate         | Cost \$         |
|--------------------|-------------|---|--------------|-----------------|
| Parts              |             |   |              | 483.00          |
| Body Labor         | 28.6 hrs    | @ | \$ 55.00 /hr | 1,573.00        |
| Paint Labor        | 19.3 hrs    | @ | \$ 55.00 /hr | 1,061.50        |
| Paint Supplies     | 19.3 hrs    | @ | \$ 30.00 /hr | 579.00          |
| Body Supplies      | 22.1 hrs    | @ | \$ 3.00 /hr  | 66.30           |
| Miscellaneous      |             |   |              | 19.00           |
| Subtotal           |             |   |              | 3,781.80        |
| Sales Tax          | \$ 3,781.80 | @ | 7.0000 %     | 264.73          |
| <b>Grand Total</b> |             |   |              | <b>4,046.53</b> |

ALL ESTIMATES ARE BASED ON VISUAL INSPECTION OF DAMAGES. THE CUSTOMER HAS THE RIGHT TO THE REPLACED PARTS, IF YOU WAIVE THAT RIGHT , INITIAL HERE \_\_\_\_\_. THE CUSTOMER HAS THE RIGHT TO INSPECT THE VEH BEFORE PAYING FOR THE REPAIRS. PARTS PRICES ARE SUBJECT TO INVOICE. ALL OUR REPAIRS CARRY A LIFETIME WARRANTY WHEN USING OEM PARTS NO WARRANTY ON ANY RUST REPAIRS. THANK YOU FOR CONSIDERING US TO REPAIR YOUR VEHICLE.

JOHN BRINTON

ALL REPAIRS MUST BE PAID IN FULL BY OWNER OR INSURANCE COMPANY BEFORE VEHICLE CAN BE RELEASED!!

AS PER N.J INSURANCE LAW TITLE 11 SUBCHAPTER 10, YOU MAY USE ANY LICENSED REPAIR FACILITY OF YOUR OWN CHOICE.

BRINTON AUTO BODY WILL NEVER INCUR ANY COSTS TO YOU BEYOND WHAT YOUR INSURANCE ALLOWS AND